

Site Name	Streetname	Town	State	Test Name	Line No	Tank No	Test Due	Frequency Months
Albany Street Bus Garage	421 Albany Street	Boston	MA	MONITORING SYSTEM (ATG)			09/29/22	12
Albany Street Bus Garage				INSPECTION				
Albany Street Bus Garage				LEAK DETECTOR TEST	3		09/29/22	12
Albany Street Bus Garage				LEAK DETECTOR TEST	4		09/29/22	12
Albany Street Bus Garage				IMPACT/SHEAR VALVE TEST	3		09/29/22	12
Albany Street Bus Garage				IMPACT/SHEAR VALVE TEST	4		09/29/22	12
Albany Street Bus Garage				EMERGENCY STOP FUNCTIONALITY TEST			09/29/22	12
Albany Street Bus Garage	275 Dorchester Avenue	South Boston	MA	OVERFILL DEVICE VERIFICATION			09/29/22	12
Cabot Yard Bus Garage				MONITORING SYSTEM (ATG)			12/14/22	12
Cabot Yard Bus Garage				INSPECTION				
Cabot Yard Bus Garage				LEAK DETECTOR TEST	6		12/14/22	12
Cabot Yard Bus Garage				LEAK DETECTOR TEST	22		12/14/22	12
Cabot Yard Bus Garage				IMPACT/SHEAR VALVE TEST	6		12/14/22	12
Cabot Yard Bus Garage				IMPACT/SHEAR VALVE TEST	22		12/14/22	12
Cabot Yard Bus Garage				EMERGENCY STOP FUNCTIONALITY TEST			12/14/22	12
Cabot Yard Bus Garage				OVERFILL DEVICE VERIFICATION			12/14/22	12
Cabot Yard Bus Garage				STAGE I PRESSURE DECAY TEST			12/10/22	12
Cabot Yard Bus Garage				STAGE I P/V VENT CAP TEST			12/10/22	12
Cabot Yard Bus Garage				STAGE I STATIC TORQUE ROTATABLE ADAPTOR TEST			12/10/22	12
Cabot Yard Bus Garage				STAGE I LEAK RATE OF DROP			12/10/22	12
Cabot Yard Bus Garage				TUBE/OVERFILL DEVICE				
Cabot Yard Auto Garage				MONITORING SYSTEM (ATG)			07/02/22	12
Cabot Yard Auto Garage				INSPECTION				
Cabot Yard Auto Garage				OVERFILL DEVICE VERIFICATION			07/02/22	12
Cabot Yard Auto Garage				STAGE I PRESSURE DECAY TEST			07/02/22	12
Cabot Yard Auto Garage				STAGE I P/V VENT CAP TEST			07/02/22	12
Charlestown Bus Storage Garage	21 Arlington Avenue	Charlestown	MA	MONITORING SYSTEM (ATG)			06/25/22	12
Charlestown Bus Storage Garage				INSPECTION				
Charlestown Bus Storage Garage				LEAK DETECTOR TEST	1		06/25/22	12
Charlestown Bus Storage Garage				LEAK DETECTOR TEST	2		06/25/22	12
Charlestown Bus Storage Garage				IMPACT/SHEAR VALVE TEST	1		06/25/22	12
Charlestown Bus Storage Garage				IMPACT/SHEAR VALVE TEST	2		06/25/22	12
Charlestown Bus Storage Garage				EMERGENCY STOP FUNCTIONALITY TEST			06/25/22	12
Charlestown Bus Storage Garage	26 Arlington Avenue	Charlestown	MA	OVERFILL DEVICE VERIFICATION			06/25/22	12
Charlestown Truck Garage				MONITORING SYSTEM (ATG)			09/29/22	12
Charlestown Truck Garage				INSPECTION				
Charlestown Truck Garage				LEAK DETECTOR TEST	10		03/11/22	12
Charlestown Truck Garage				LEAK DETECTOR TEST	12		03/11/22	12
Charlestown Truck Garage				IMPACT/SHEAR VALVE TEST	9		03/11/22	12
Charlestown Truck Garage				IMPACT/SHEAR VALVE TEST	10		03/11/22	12
Charlestown Truck Garage				IMPACT/SHEAR VALVE TEST	11		03/11/22	12
Charlestown Truck Garage				IMPACT/SHEAR VALVE TEST	12		03/11/22	12
Charlestown Truck Garage				OVERFILL DEVICE VERIFICATION			09/29/22	12
Charlestown Truck Garage				STAGE I PRESSURE DECAY TEST			03/11/22	12
Charlestown Truck Garage				STAGE I P/V VENT CAP TEST			03/11/22	12
Charlestown Truck Garage				STAGE I VAPOR TIE TEST			03/11/22	12
Charlestown Truck Garage				STAGE I STATIC TORQUE ROTATABLE ADAPTOR TEST			03/11/22	12
Charlestown Truck Garage				STAGE I LEAK RATE OF DROP			03/11/22	12
Charlestown Truck Garage				TUBE/DRAIN VALVE				
Charlestown Bus Maintenance				MONITORING SYSTEM (ATG)			06/28/22	12
Charlestown Bus Maintenance				INSPECTION				
Fellsway Bus Garage	465 Salem Street	Medford	MA	MONITORING SYSTEM (ATG)			06/25/22	12
Fellsway Bus Garage				INSPECTION				
Fellsway Bus Garage				LEAK DETECTOR TEST	1		06/25/22	12
Fellsway Bus Garage				LEAK DETECTOR TEST	2		06/25/22	12
Fellsway Bus Garage				IMPACT/SHEAR VALVE TEST (FACILITY)			06/25/22	12
Fellsway Bus Garage				EMERGENCY STOP FUNCTIONALITY TEST			06/25/22	12
Fellsway Bus Garage	985 Western Avenue	Lynn	MA	OVERFILL DEVICE VERIFICATION			06/25/22	12
Lynn Bus Garage				MONITORING SYSTEM (ATG)			06/25/22	12
Lynn Bus Garage				INSPECTION				
Lynn Bus Garage				IMPACT/SHEAR VALVE TEST (FACILITY)			06/25/22	12
Lynn Bus Garage				EMERGENCY STOP FUNCTIONALITY TEST			06/25/22	12
Lynn Bus Garage				OVERFILL DEVICE VERIFICATION			06/25/22	12
Quincy Bus Garage				MONITORING SYSTEM (ATG)			07/02/22	12
Quincy Bus Garage				INSPECTION				
Quincy Bus Garage				LEAK DETECTOR TEST	9		07/02/22	12
Quincy Bus Garage				LEAK DETECTOR TEST	10		07/02/22	12
Quincy Bus Garage				IMPACT/SHEAR VALVE TEST	9		07/02/22	12
Quincy Bus Garage				IMPACT/SHEAR VALVE TEST	10		07/02/22	12
Quincy Bus Garage	954 Hancock Street	Quincy	MA	EMERGENCY STOP FUNCTIONALITY TEST			07/02/22	12
Quincy Bus Garage				OVERFILL DEVICE VERIFICATION			07/02/22	12
Quincy Bus Garage				STAGE I PRESSURE DECAY TEST			07/02/22	12
Quincy Bus Garage				STAGE I P/V VENT CAP TEST			07/02/22	12
Quincy Bus Garage				STAGE I STATIC TORQUE ROTATABLE ADAPTOR TEST			07/02/22	12
Quincy Bus Garage				STAGE I LEAK RATE OF DROP			07/02/22	12
Quincy Bus Garage				TUBE/OVERFILL DEVICE				
Southampton Bus Garage-Fuel Alley				MONITORING SYSTEM (ATG)			06/28/22	12
Southampton Bus Garage-Fuel Alley				INSPECTION (Fuel Alley)				
Southampton Bus Garage-Fuel Alley				MONITORING SYSTEM (ATG)			06/28/22	12
Southampton Bus Garage-Fuel Alley				INSPECTION (Parts Room)				
Southampton Bus Garage-Fuel Alley				IMPACT/SHEAR VALVE TEST	1		06/28/22	12
Southampton Bus Garage-Fuel Alley				OVERFILL DEVICE VERIFICATION			06/28/22	12
Cabot Yard / CNG Fueling Station	275 Dorchester Avenue	South Boston	MA	MONITORING SYSTEM (ATG)			07/13/22	12
Cabot Yard / CNG Fueling Station				INSPECTION				
Cabot Yard / CNG Fueling Station				LEAK DETECTOR TEST	8		07/13/22	12

Cabot Yard / CNG Fueling Station				IMPACT/SHEAR VALVE TEST	8	07/13/22	12
Andrew Square Station	496 Southampton Street	South Boston	MA	MONITORING SYSTEM (ATG) INSPECTION		05/28/22	12
Andrew Square Station				OVERFILL DEVICE VERIFICATION		05/28/22	12
Quincy Adams Station	Burgin Parkway and Center Street	Quincy	MA	MONITORING SYSTEM (ATG) INSPECTION		05/28/22	12
Quincy Adams Station	Burgin Parkway and Center Street	Quincy	MA	OVERFILL DEVICE VERIFICATION		05/28/22	12
South Boston New Power Station	696 East First Street	South Boston	MA	MONITORING SYSTEM (ATG) INSPECTION		08/05/22	12
South Boston New Power Station				OVERFILL DEVICE VERIFICATION		08/05/22	12